


Photographs showing PCB locations inside case.



ROGERS LABS, INC.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214



Garmin International, Inc.  
MODEL: 011-01450-xx  
Test #:060712 SN: 45  
Test to: FCC Parts 2 and 15.249,

FCC ID#: IPH-01074  
IC:1792A-01074  
RSS-210


Page 1 of 4

IPH 01074 Tx Internal Photos.Doc 7/24/2006

Internal photographs of transmitter section of equipment under test.  
Transmitter section without covers



Printed Circuit boards with covers in place.



ROGERS LABS, INC.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214



Garmin International, Inc.  
MODEL: 011-01450-xx  
Test #:060712 SN: 45  
Test to: FCC Parts 2 and 15.249,

FCC ID#: IPH-01074  
IC:1792A-01074  
RSS-210

Page 3 of 4

IPH 01074 Tx Internal Photos.Doc 7/24/2006

# Printed Circuit boards with covers removed



Lower Left Corner is SD card memory slot.

ROGERS LABS, INC.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214

Garmin International, Inc.  
MODEL: 011-01450-xx  
Test #:060712 SN: 45  
Test to: FCC Parts 2 and 15.249,

FCC ID#: IPH-01074  
IC:1792A-01074  
RSS-210

Page 4 of 4

IPH 01074 Tx Internal Photos.Doc 7/24/2006